

Acuity

LogMar
x 10

10/100

F P

10

10/70

T O Z

8.5

10/50

L P E D

7

10/40

P E C F D

6

10/30

E D F C Z P

4.8

10/25

F E L O P Z D

4

10/20

D E F P O T E C

3

10/15

L E F O D P C T

1.8

10/13

F D P L T C E O

1.1

10/10

P E Z O L C F T D

0